Insteon - Bug #861

Cannot observe battery powered sensor events

10/15/2014 07:07 AM - Luke Murphey

| Closed | Start date: | 10/15/2014 |
|--|------------------------|--|
| Normal | Due date: | |
| Luke Murphey | % Done: | 100% |
| | Estimated time: | 0.00 hour |
| 0.5 | | |
| | | |
| or events that indicate if a sensor tripped. | | |
| | Normal Luke Murphey | Normal Due date: Luke Murphey % Done: Estimated time: 0.5 |

History

#1 - 10/15/2014 04:19 PM - Luke Murphey

- Determine if sensor signals are being provided by the PLM to the modular input
- Determine if HouseLinc sees the signals

#2 - 10/17/2014 06:40 AM - Luke Murphey

I have the events stored here:

http://127.0.0.1:8000/en-US/app/insteon/search?sid=rt_1413527908.9

#3 - 10/17/2014 06:43 AM - Luke Murphey

Better one:

http://127.0.0.1:8000/en-US/app/insteon/search?sid=1413528074.12

#4 - 10/24/2014 08:27 AM - Luke Murphey

- Status changed from New to Closed

- % Done changed from 0 to 100