

Insteon - Bug #861

Cannot observe battery powered sensor events

10/15/2014 07:07 AM - Luke Murphey

Status:	Closed	Start date:	10/15/2014
Priority:	Normal	Due date:	
Assignee:	Luke Murphey	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:	0.5		
Description			
I'm not seeing the sensor events that indicate if a sensor tripped.			

History

#1 - 10/15/2014 04:19 PM - Luke Murphey

- Determine if sensor signals are being provided by the PLM to the modular input
- Determine if HouseLinc sees the signals

#2 - 10/17/2014 06:40 AM - Luke Murphey

I have the events stored here:

http://127.0.0.1:8000/en-US/app/insteon/search?sid=rt_1413527908.9

#3 - 10/17/2014 06:43 AM - Luke Murphey

Better one:

<http://127.0.0.1:8000/en-US/app/insteon/search?sid=1413528074.12>

#4 - 10/24/2014 08:27 AM - Luke Murphey

- Status changed from New to Closed

- % Done changed from 0 to 100